

Attachment A: Digital Images

Page 1 of 6

May 19th, 2008

BOE Building 2427 and 2428 Clearance

Sacramento, CA



- 1) Image of containment leading to area 2427 within BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of wallboard removal within 2427 at time of clearance inspection and sampling assessment.



- 3) Image of air sampling equipment staged by BioMax and HTI within containment area 2427 at time of assessment.



- 4) Image of physical wallboard removal as viewed from 2427.



- 5) Image within containment system of filtered intake air element and location within 2427 plastic barriers at time of assessment.



- 6) Additional image within 2427 containment of ceiling barrier system and support structures as prescribed by BioMax.



- 7) Close-up image of wall framing and sheetrock edge material within 2427 containment system.



- 8) Image of left wall side within 2427 containment space located along west hallway adjacent to containment area.



9) Image of air sampling equipment location within hallway outside containment area at time of assessment.



10) Image in hallway looking toward northeastern corner of building where air sampling location was performed for comparative purposes.



11) Image of air sampling equipment / location within hallway outside containment area at time of assessment.



12) Image of ambient air sampling location on 4th floor garage rooftop as performed for ambient background comparative purposes.